






























































TALBOT

Type	Diam.	Vers.	Date	Notes	Kit	Kit+Piston	Piston	Kit+K Piston	K Piston	Guide Kit	Bak Kit	SuperKit
1307-1510												
 Simca 1510 1.6	54	Bendix	1978-10->1983-12		254103	254965	P544702					
 Simca 1510 1.4	54	Bendix	1980-01->1984-04		254103	254965	P544702					
 1510 1.6	54	Bendix	1981-07->1982-06		254103	254965	P544702					
 Simca 1307 1.3S		Bendix	1975-07->1978-12								900939	
 Simca 1307 1.3		Bendix	1975-07->1981-08								900939	
 Simca 1510 1.6		Bendix	1978-10->1983-12								900939	
 Simca 1308 1.4		Bendix	1978-11->1981-08								900939	
160												
 1.6	22		1973-01->1979-03		422010							
 1.6	28.6		1973-01->1979-03		528001							
180												
 2.0	22		1973-02->1977-09		422010							
 1.8	22		1982-01->1982-12		422010							
 1.9 D	22		1982-01->1982-12		422010							
 2.0	28.6		1973-02->1977-09		528001							
 1.9 D	28.6		1982-01->1982-12		528001							
 1.8	28.6		1982-01->1982-12		528001							
HORIZON												
 1.3	20.6	Bendix	1978-02->1986-06		120006							
 1.1	20.6	Bendix	1979-01->1984-09		120006							
 1.4	20.6	Bendix	1979-07->1986-06		120006							
 1.6	20.6	Bendix	1982-07->1986-06		120006							
 1.9 Diesel	20.6	Bendix	1982-07->1986-06		120006							





















Type	Diam.	Vers.	Date	Notes	Kit	Kit+Piston	Piston	Kit+K Piston	K Piston	Guide Kit	Bak Kit	SuperKit
HORIZON												
1.6	20.6	Bendix	1982-07->1986-06		120008							
1.9 Diesel	20.6	ATE (Teves)	1982-07->1986-06		120016							
1.6	20.6	ATE (Teves)	1982-07->1986-06		120016							
1.3	48	Lucas	1978-02->1986-06		248002	248931	P482901					
1.3	48	Bendix	1978-02->1986-06		248002	248990	P482903					
1.3	48	ATE (Teves)	1978-02->1986-06		248017	248947	P483001					
1.3	48	Girling	1978-02->1986-06		248030	248932	P482901					
1.1	48	Lucas	1979-01->1984-09		248002	248931	P482901					
1.1	48	Bendix	1979-01->1984-09		248002	248990	P482903					
1.1	48	ATE (Teves)	1979-01->1984-09		248017	248947	P483001					
1.1	48	Girling	1979-01->1984-09		248030	248932	P482901					
1.4	48	Lucas	1979-07->1986-06		248002	248931	P482901					
1.4	48	Bendix	1979-07->1986-06		248002	248990	P482903					
1.4	48	ATE (Teves)	1979-07->1986-06		248017	248947	P483001					
1.4	48	Girling	1979-07->1986-06		248030	248932	P482901					
1.6	48	Lucas	1982-07->1986-06		248002	248931	P482901					
1.9 Diesel	48	Lucas	1982-07->1986-06		248002	248931	P482901					
1.9 Diesel	48	Bendix	1982-07->1986-06		248002	248990	P482903					
1.6	48	Bendix	1982-07->1986-06		248002	248990	P482903					
1.6	48	Girling	1982-07->1986-06		248030	248932	P482901					
1.9 Diesel	48	Girling	1982-07->1986-06		248030	248932	P482901					





















TALBOT

Type	Diam.	Vers.	Date	Notes	Kit	Kit+Piston	Piston	Kit+K Piston	K Piston	Guide Kit	Bak Kit	SuperKit
HORIZON												
 1.3	20.6	Bendix	1978-02->1986-06		320008							
 1.1	20.6	Bendix	1979-01->1984-09		320008							
 1.4	20.6	Bendix	1979-07->1986-06		320008							
 1.9 Diesel	20.6	Bendix	1982-07->1986-06		320008							
 1.6	20.6	Bendix	1982-07->1986-06		320008							
 1.3	19	Lucas	1978-02->1986-06		419044							
 1.3	19	Bendix	1978-02->1986-06	Spain	419049							
 1.1	19	Lucas	1979-01->1984-09		419044							
 1.1	19	Bendix	1979-01->1984-09	Spain	419049							
 1.4	19	Lucas	1979-07->1986-06		419044							
 1.4	19	Bendix	1979-07->1986-06	Spain	419049							
 1.6	19	Lucas	1982-07->1986-06		419044							
 1.9 Diesel	19	Lucas	1982-07->1986-06		419044							
 1.6	19	Bendix	1982-07->1986-06	Spain	419049							
 1.9 Diesel	19	Bendix	1982-07->1986-06	Spain	419049							
 1.3	25.4	Bendix	1978-02->1986-06		525011							
 1.3	25.4	Lucas	1978-02->1986-06		525013							
 1.1	25.4	Bendix	1979-01->1984-09		525011							
 1.1	25.4	Lucas	1979-01->1984-09		525013							
 1.4	25.4	Bendix	1979-07->1986-06		525011							
 1.4	25.4	Lucas	1979-07->1986-06		525013							


















Type	Diam.	Vers.	Date	Notes	Kit	Kit+Piston	Piston	Kit+K Piston	K Piston	Guide Kit	Bak Kit	SuperKit
HORIZON												
 1.9 Diesel	25.4	Bendix	1982-07->1986-06		525011							
 1.6	25.4	Bendix	1982-07->1986-06		525011							
 1.6	25.4	Lucas	1982-07->1986-06		525013							
 1.9 Diesel	25.4	Lucas	1982-07->1986-06		525013							
MATRA BAGHEERA												
 1.3 (X3550)	48	ATE (Teves)	1974-01->1978-03		248017	248947	P483001					
 1.4 (X6550)	48	ATE (Teves)	1975-12->1979-11		248017	248947	P483001					
 1.4 (X6)	48	ATE (Teves)	1979-11->1980-09		248017	248947	P483001					
 1.4 (X6)	48	Girling	1979-11->1980-09		248030	248932	P482901					
 1.3 (X3550)	45	Bendix	1974-01->1978-03		245029	245935	P454503					
 1.4 (X6550)	45	Bendix	1975-12->1979-11		245029	245935	P454503					
 1.4 (X6)	45	Bendix	1979-11->1980-09		245029	245935	P454503					
 1.3 (X3550)	54	Bendix	1974-01->1978-03		254029							
 1.4 (X6550)	54	Bendix	1975-12->1979-11		254029							
 1.4 (X6)	54	Bendix	1979-11->1980-09		254029							
MURENA												
 2.1	45	Bendix	1980-09->1984-07		245029	245935	P454503					
 1.6	45	Bendix	1981-08->1985-01		245029	245935	P454503					
 2.1 S	45	Bendix	1983-04->1985-01		245029	245935	P454503					
 2.1	54	Bendix	1980-09->1984-07		254029							
 1.6	54	Bendix	1981-08->1985-01		254029							
 2.1 S	54	Bendix	1983-04->1985-01		254029							

TALBOT

Type	Diam.	Vers.	Date	Notes	Kit	Kit+Piston	Piston	Kit+K Piston	K Piston	Guide Kit	Bak Kit	SuperKit
RANCHO												
 1.4	48	ATE (Teves)	1977-01->1984-07		248017	248947	P483001					
 1.4	48	Girling	1977-01->1984-07		248030	248932	P482901					
SAMBA												
 0.9 (51A601, 51A591)	19	Bendix	1981-01->1985-12		119001							
 0.9 (51A601, 51A591)	19	Lucas	1981-01->1985-12		119008							
 1.1 (51A611, 51A702)	19	Bendix	1981-01->1986-06		119001							
 1.4 (51A632)	19	Bendix	1981-01->1986-06		119001							
 1.1 (51A611, 51A702)	19	Lucas	1981-01->1986-06		119008							
 1.4 (51A632)	19	Lucas	1981-01->1986-06		119008							
 1.2 Rallye (51A692)	19	Bendix	1983-01->1986-10		119001							
 1.4 Rallye (51A642)	19	Bendix	1983-01->1986-10		119001							
 1.2 Rallye (51A692)	19	Lucas	1983-01->1986-10		119008							
 1.4 Rallye (51A642)	19	Lucas	1983-01->1986-10		119008							
 1.4 (51A642)	19	Bendix	1983-06->1986-10		119001							
 1.4 (51A642)	19	Lucas	1983-06->1986-10		119008							
 0.9 (51A601, 51A591)	22.2	TRW	1981-01->1985-12		322012							
 0.9 (51A601, 51A591)	22.2	Bendix	1981-01->1985-12		322013							
 1.4 (51A632)	22.2	TRW	1981-01->1986-06		322012							
 1.1 (51A611, 51A702)	22.2	TRW	1981-01->1986-06		322012							
 1.4 (51A632)	22.2	Bendix	1981-01->1986-06		322013							
 1.1 (51A611, 51A702)	22.2	Bendix	1981-01->1986-06		322013							
 1.4 Rallye (51A642)	22.2	TRW	1983-01->1986-10		322012							

Type	Diam.	Vers.	Date	Notes	Kit	Kit+Piston	Piston	Kit+K Piston	K Piston	Guide Kit	Bak Kit	SuperKit
SAMBA												
 1.2 Rallye (51A692)	22.2	TRW	1983-01->1986-10		322012							
 1.2 Rallye (51A692)	22.2	Bendix	1983-01->1986-10		322013							
 1.4 Rallye (51A642)	22.2	Bendix	1983-01->1986-10		322013							
 1.4 (51A642)	22.2	TRW	1983-06->1986-10		322012							
 1.4 (51A642)	22.2	Bendix	1983-06->1986-10		322013							
SAMBA Descaptable												
 1.4 (51E642)	19	Bendix	1981-01->1986-06		119001							
 1.4 (51E642)	19	Lucas	1981-01->1986-06		119008							
 1.4 (51E642)	22.2	TRW	1981-01->1986-06		322012							
 1.4 (51E642)	22.2	Bendix	1981-01->1986-06		322013							
SIMCA 1000												
 0.9 GL, GLS	22.2	Bendix	1961-10->1972-05	S.C.	122068							
 0.9	22.2	Bendix	1961-10->1975-09	S.C.	122068							
 1.1 Spezial	22.2	Bendix	1968-10->1975-09	S.C.	122068							
 1.1 Rallye	22.2	Bendix	1970-10->1972-09	S.C.	122068							
 0.9 LS, GL	22.2	Bendix	1970-10->1975-09	S.C.	122068							
 1.3 Rallye 2	22.2	Bendix	1972-09->1977-09	S.C.	122068							
 1.3 Rallye 1	22.2	Bendix	1972-10->1977-09	S.C.	122068							
 1.3 Spezial	22.2	Bendix	1974-08->1977-09	S.C.	122068							
 1005 LS, GLS	22.2	Bendix	1976-10->1978-07	S.C.	122068							
 1006 SR, GLS	22.2	Bendix	1976-10->1978-07	S.C.	122068							
 1.3 Rallye 3	22.2	Bendix	1978-01->1978-12	S.C.	122068							

TALBOT

Type	Diam.	Vers.	Date	Notes	Kit	Kit+Piston	Piston	Kit+K Piston	K Piston	Guide Kit	Bak Kit	SuperKit
SIMCA 1000												
 1.1 Spezial	44	ATE (Teves)	1968-10->1975-09		244001							
 1.1 Spezial	44	ATE (Teves)	1968-10->1975-09		244004	244922	P442901					
 1.1 Rallye	44	ATE (Teves)	1970-10->1972-09		244001							
 1.1 Rallye	44	ATE (Teves)	1970-10->1972-09		244004	244922	P442901					
 0.9 LS,GL	44	ATE (Teves)	1970-10->1975-09		244004	244922	P442901					
 1.3 Rallye 1	44	ATE (Teves)	1972-10->1977-09		244004	244922	P442901					
 1.3 Rallye 2	48	ATE (Teves)	1972-09->1977-09		248017	248947	P483001					
 1.3 Rallye 3	48	ATE (Teves)	1978-01->1978-12		248017	248947	P483001					
 0.9 GL,GLS	25.4		1961-10->1972-05		525014							
 0.9	25.4		1961-10->1975-09		525014							
SIMCA 1100 Break/Tourisme												
 1.1	19	Lucas	1968-10->1980-01		119064							
 1.3 Spezial	19	Lucas	1974-07->1976-11		119064							
 1.1	48	ATE (Teves)	1968-10->1980-01		248017	248947	P483001					
 1.3 Spezial	48	ATE (Teves)	1974-07->1976-11		248017	248947	P483001					
 1.3 Spezial	48	Girling	1974-07->1976-11		248030	248932	P482901					
 1.1	25.4	Lucas	1968-10->1980-01		525012							
 1.3 Spezial	25.4	Lucas	1974-07->1976-11		525012							
SIMCA 1100 Fastback												
 1.1 LS,GLS	19	Lucas	1968-10->1977-09		119064							
 0.9 LS	19	Lucas	1970-10->1972-05		119064							
 1.2 Spezial	19	Lucas	1971-10->1977-09		119064							

Type	Diam.	Vers.	Date	Notes	Kit	Kit+Piston	Piston	Kit+K Piston	K Piston	Guide Kit	Bak Kit	SuperKit
SIMCA 1100 Fastback												
1.3 Spezial TI	19	Lucas	1972-10->1977-09		119064							
1.1 LE,LX,GLS,ES	19	Lucas	1976-10->1980-01		119064							
0.9 LE	19	Lucas	1976-10->1980-01		119064							
1.1 LS,GLS	48	ATE (Teves)	1968-10->1977-09		248017	248947	P483001					
0.9 LS	48	ATE (Teves)	1970-10->1972-05		248017	248947	P483001					
1.2 Spezial	48	ATE (Teves)	1971-10->1977-09		248017	248947	P483001					
1.3 Spezial TI	48	ATE (Teves)	1972-10->1977-09		248017	248947	P483001					
0.9 LE	48	ATE (Teves)	1976-10->1980-01		248017	248947	P483001					
1.1 LE,LX,GLS,ES	48	ATE (Teves)	1976-10->1980-01		248017	248947	P483001					
1.1 LS,GLS	25.4	Lucas	1968-10->1977-09		525012							
0.9 LS	25.4	Lucas	1970-10->1972-05		525012							
1.2 Spezial	25.4	Lucas	1971-10->1977-09		525012							
1.3 Spezial TI	25.4	Lucas	1972-10->1977-09		525012							
1.1 LE,LX,GLS,ES	25.4	Lucas	1976-10->1980-01		525012							
0.9 LE	25.4	Lucas	1976-10->1980-01		525012							
SIMCA 1200 S Coupé												
1.2	19	Lucas	1968-10->1972-03		119064							
1.2	19	TRW	1968-10->1972-03		319060							
1.2	19	Lucas	1968-10->1972-03		419045							
1.2	19	Bendix	1968-10->1972-03		419049							
1.2	25.4	Lucas	1968-10->1972-03		525012							

REPAIR KITS LITS BY MARKES AND MODELS

TALBOT

Type	Diam.	Vers.	Date	Notes	Kit	Kit+Piston	Piston	Kit+K Piston	K Piston	Guide Kit	Bak Kit	SuperKit
SIMCA 1301												
⊗▶ 1.3 Spezial			1970-10->1976-11								901800	
SIMCA 1301 Tourisme												
⊗▶ 1.3 Spezial			1970-10->1972-07								901800	
SOLARA												
◀⊗ 1.6	54	Bendix	1980-02->1986-07		254103	254965	P544702					
◀⊗ 1.3	54	Bendix	1980-02->1986-07		254103	254965	P544702					